




ASSEMBLY INSTRUCTION

H08-RZ-US3001MO


Ex1




①



Wait 72 hours for rebound




E




F


Fx1



②



③



Cx1

