















Assembly Instructions

<p>A</p>  <p>1X</p>	<p>G</p>  <p>5X</p>
<p>B</p>  <p>1X</p>	<p>H</p>  <p>M6X20MM</p> <p>4X</p>
<p>C</p>  <p>2X</p>	<p>I</p>  <p>M6X30MM</p> <p>4X</p>
<p>D</p>  <p>1X</p>	<p>J</p>  <p>M8X65MM</p> <p>4X</p>
<p>E</p>  <p>1X</p>	<p>K</p>  <p>4X</p>
<p>F</p>  <p>1X</p>	<p>L</p>  <p>1X</p>
	<p>M</p>  <p>1X</p>
	<p>N</p>  <p>4X</p>

